

Fitness Certificate

| | |
|---|---|
| 1. Name of the Officer | Ankit Kumar, Assistant Engineer |
| 2. Name of the School | Maharishi Vidhya Mandir |
| 3. Location with name of Education Distt/Sub-Dist | Village-Tashka Near Govt. Polytechnic, Rampur(U.P) |
| 4. Classification of Building as specified in column 4 of the application for fitness certificate and size Number of Building-1 | Size:- L103.8m, width 8.12m, Height 7.50m Year:- 1998 |
| 5. Period for which the certificate issued | Two year |
| 6. Nature of Defects, if any | |
| a) Foundation and basement | No defect |
| b) Superstructure | No defect |
| c) Doors and windows | No defect |
| d) Wood work wrought and put up | No defect |
| e) Roof | No defect |
| f) Flooring | No defect |
| g) Miscellaneous(Cracks,etc) | Miner |
| 7. Any major defects noticed which will render the building unsafe in any manner | No |
| 8. Whether maintenance works have been done properly | Yes |
| 9. Whether the structure is sound or not for conducting classes | Sound |


CERTIFICATE

Letter No- 29 /Inspection/23

Date- 01/03/2023

certified that the school building has been inspected on 01.03.2023 by Ankit Kumar, Assistant Engineer CD PWD Rampur and found to be fit to conduct classes, for the period two year (w.e.f. 01.03.2023) for the reasons stated above.

Place: Rampur
Date: 01.03.2023


01/03/23
Assistant Engineer
C.D.P.W.D. RAMPUR